

www.aucklandhomecheck.co.nz enquires@aucklandhomecheck.co.nz PO Box 137280 Parnell 09 377 1086 021 284 1728

Building Report



PROPERTY SITED AT

4 Percy Green Silverdale



Date of Inspection 21 October 2016

House Inspection for

HOUSE INSPECTION AT 4 Percy Green Silverdale

After my recent inspection at the above property we submit our findings as follows.

- The house is approx 2 years old.
- Built with a colourstell roof.
- Timber weatherboard exterior.
- Aluminium joinery.
- Concrete floor
- Concrete foundation.
- $_{\odot}$ $\,$ The section has been cut and filled to level building platform.

Weather conditions at the time of inspection – Fine

Present at the time of inspection -

Real Estate Agent Bob Hodges, Auckland Home Check Ltd

This report contains references to the "moisture content" of internal finishing timber and other timber components of the building. Moisture content is given as a percentage (%). Timber considered "dry" in the building sense, will have a moisture content equal to or less than 16%. Although higher moisture readings may be acceptable in some circumstances, any readings greater than about 18% in a completed building should be investigated further.



ENTRANCE & HALLWAY	Front Door	A B C D R MR ☑ □ □ □ □ □ □	
	Walls		Gib Board / Paint Finish
HALI	Ceiling		Moisture Readings at Skirting Board 14% max Gib Board / Paint Finish
CE &	Floor Coverings		Tiles
RAN	Windows		Aluminium
ENT	Electrical		
	Cupboard Doors		
	Doors		NA
	Walls		
	Ceiling		
STAIRS	Floor Coverings		
ST	Windows		
	Electrical		

A- Very Good B-Good C- Will Need Attention Soon D- Needs Attention Now R- Needs Minor Repair MR- Major Repair Required

Comments:

The entryways are in good condition. No significant defects visible.







	Doors	A B C D R MR	
	Walls		Gib Board / Paint Finish Gib Board / Paint Finish
	Ceiling		Tiles
	Floor Coverings		
KITCHEN	Windows		Aluminium
	Electrical		Malhaan
Y	Cabinetry		Melteca
	Bench Tops		Engineered stone
	Hobb/Oven		Gas top
	Waste master		
	Range hood		

A- Very Good B-Good C- Will Need Attention Soon D- Needs Attention Now R- Needs Minor Repair MR- Major Repair Required

Comments:

The kitchen is in good condition. All appliances and fittings are in good working order.





	Doors	A B C D R MR ☑ □ □ □ □ □	
	Walls		Gib Board / Paint Finish Maieture Boadings at Skirting Board 12% may
LOUNGE	Ceiling		Moisture Readings at Skirting Board 13% max Gib Board / Paint Finish
гоп	Floor Coverings		Carpet
	Windows		Aluminium
	Electrical		
	Doors		
	Walls		Gib Board / Paint Finish
g	Ceiling		Moisture Readings at Skirting Board 11% max Gib Board / Paint Finish
VINIC	, J		
DINING	Floor Coverings		Tiles
DININ			

A- Very Good B-Good C- Will Need Attention Soon D- Needs Attention Now R- Needs Minor Repair MR- Major Repair Required

Comments:

The lounge and dining areas are in good condition. All moisture readings are well within acceptable limits.





www.aucklandhomecheck.co.nz 09 377 1086 enquires@aucklandhomecheck.co.nz 021 284 1728 PO Box 137280




	Doors	A B C D R MR ☑ □ □ □ □ □ □	
-	Walls		Gib Board / Paint Finish Moisture Readings at Skirting Board 12% max
NOO	Ceiling		Gib Board / Paint Finish
BEDROOM	Floor Coverings		Carpet
8	Windows		Aluminium
	Electrical		
	Doors		
5	Walls		Gib Board / Paint Finish
	Ceiling		Moisture Readings at Skirting Board 10% max Gib Board / Paint Finish
BEDROOM	Floor Coverings		Carpet
BE	Windows		Aluminium
	Electrical		

A- Very Good B-Good C- Will Need Attention Soon D- Needs Attention Now R- Needs Minor Repair MR- Major Repair Required

Comments:

All moisture readings are well within acceptable limits. Retaining wall behind bedroom 1 shows no detectable signs of dampness.



www.aucklandhomecheck.co.nz 09 377 1086 enquires@aucklandhomecheck.co.nz 021 284 1728 PO Box 137280



	Doors	A B C D R MR ☑ □ □ □ □ □ □	
e	Walls		Gib Board / Paint Finish Moisture Readings at Skirting Board 10% max
MOO	Ceiling		Gib Board / Paint Finish
BEDROOM	Floor Coverings		Carpet
8	Windows		Aluminium
	Electrical		
	Doors		
	Walls		Gib Board / Paint Finish
OM 4	Ceiling		Moisture Readings at Skirting Board 10% max Gib Board / Paint Finish
BEDROOM	Floor Coverings		Carpet
BE	Windows		Aluminium
	ei		
	Electrical		

A- Very Good B-Good C- Will Need Attention Soon D- Needs Attention Now R- Needs Minor Repair MR- Major Repair Required

Comments:

All moisture readings are well within acceptable limits.





	Doors	A B C D R MR ☑ □ □ □ □ □ □	
No	Walls		Gib Board / Paint Finish Moisture Readings at Skirting Board 13% max
/ RO	Ceiling		Gib Board / Paint Finish
FAMILY ROOM	Floor Coverings		Carpet
Ч	Windows		Aluminium
	Electrical		
	Doors		
	Walls		
	Ceiling		
	Floor Coverings		
	Windows		
	Electrical		

A- Very Good B-Good C- Will Need Attention Soon D- Needs Attention Now R- Needs Minor Repair MR- Major Repair Required

Comments:

The familyroom is in good condition. All moisture readings are well within acceptable limits. Skylights show no detectable signs of leaking.







	Doors	A B C D R MR ☑ □ □ □ □ □	
	Walls		Gib Board / Paint Finish
	Ceiling		Gib Board / Paint Finish
N	Floor Coverings		Tiles
BATHROOM	Windows		Aluminium
	Electrical		
	Vanity		
	Shower		
	Toilet		
	Bath		

A- Very Good B-Good C- Will Need Attention Soon D- Needs Attention Now R- Needs Minor Repair MR- Major Repair Required

Comments:

The bathroom is in good condition.

All plumbing and fittings are in good working order.





	Doors	A B C D R MR ☑ □ □ □ □ □	
	Walls		Gib Board / Paint Finish
	Ceiling		Gib Board / Paint Finish
ш	Floor Coverings		Tiles
ENSUITE	Windows		Aluminium
	Electrical		
	Vanity		
	Shower		
	Toilet		

A- Very Good B-Good C- Will Need Attention Soon D- Needs Attention Now R- Needs Minor Repair MR- Major Repair Required

Comments:

The ensuite is in good condition.

All plumbing and fittings are in good working order.



	Door	A B C D R MR ☑ □ □ □ □ □ □	
	Walls		Gib Board / Paint Finish
	Ceiling		Gib Board / Paint Finish
TOILET	Floor Coverings		Tiles
10	Windows		NA
	Electrical		
	Toilet		
	Vanity		

A- Very Good B-Good C- Will Need Attention Soon D- Needs Attention Now R- Needs Minor Repair MR- Major Repair Required

Comments:

The toilet is in good condition.

All plumbing and fittings are in good working order.





	Doors	A B C D R MR ☑ □ □ □ □ □	
	Walls		Gib Board / Paint Finish
ЛΥ	Ceiling		Gib Board / Paint Finish
LAUNDRY	Floor Coverings		Tiles
2	Windows		
	Electrical		
	Tub		
	Doors		
	Walls		Gib Board / Paint Finish
AGE	Ceiling		Gib Board / Paint Finish
GARAGE	Floor Coverings		Concrete
	Windows		Aluminium
	Electrical		

A- Very Good B-Good C- Will Need Attention Soon D- Needs Attention Now R- Needs Minor Repair MR- Major Repair Required

Comments:

The laundry and garage are in good condition.







Exterior

ELEVATION	Cladding	A B C D R MR ☑ □ □ □ □ □ □	Timber weatherboards
	Joinery		Aluminium
NORTH EL	Base Cladding		Concrete
NO			
Z	Cladding		Timber weatherboards
ATIC	Joinery		Aluminium
EAST ELEVATION	Base Cladding		Concrete

A- Very Good B-Good C- Will Need Attention Soon D- Needs Attention Now R- Needs Minor Repair MR- Major Repair Required

Comments:

The timber weather boards are well painted and have been fixed over a ventilated cavity system.

The aluminium windows all have head flashings and are weathertight. Keep exterior door sills and tracks clean and free of debris to help prevent moisture ingress.





Exterior

ELEVATION	Cladding	A B C D R MR ☑ □ □ □ □ □	Timber weatherboards
	Joinery		Aluminium
WEST EL	Base Cladding		Concrete
lion	Cladding		Timber weatherboards
EVA.	Joinery		Aluminium
SOUTH ELEVATION	Base Cladding		Concrete
SOI			

A- Very Good B-Good C- Will Need Attention Soon D- Needs Attention Now R- Needs Minor Repair MR- Major Repair Required

Comments:

The timber weather boards are well painted and have been fixed over a ventilated cavity system.

The aluminium windows all have head flashings and are weathertight.





Exterior

	Slope	A B C D R MR	Cut & retained to near level building site
SITE	Fencing		Timber
SI	Paths/Driveway		Concrete
	Surface Water		
	Material		Concrete & grass courtyard
S	Piles		
STEPS	Joists		
KS &	Decking		
DECKS	Steps		
	Handrail		

A- Very Good B-Good C- Will Need Attention Soon D- Needs Attention Now R- Needs Minor Repair MR- Major Repair Required

Comments:

The section has been cut and filled to a near level building site.

The timber retaining wall is stable and in good condition.





Roof

	Soffit	A B C D R MR ☑ □ □ □ □ □ □	
'ES	Fascia		Coloursteel
EAVES	Gutter		Coloursteel
	Downpipes		PVC
	Material		Coloursteel
	Slope		
ROOF	Flashings		
	Fixings		
	Penetrations		

A- Very Good B-Good C- Will Need Attention Soon D- Needs Attention Now R- Needs Minor Repair MR- Major Repair Required

Comments:

The coloursteel roof is in good condition. There are no signs of possible leaks.

Recommend cleaning roof.







111	Construction	A B C D R MR ☑ □ □ □ □ □ □	Timber trusses
PACE	Dampness		Dry
S S	Insulation		Yellow Batts
EILIN	Insects & Pests		Nil
σ	Rotting Timbers		Nil

A- Very Good B-Good C- Will Need Attention Soon D- Needs Attention Now R- Needs Minor Repair MR- Major Repair Required

Comments:

The roof is framed with timber trusses. There are no signs of decay or borer in the framing.

The ceiling is insulated with fiberglass batts.





Subfloor

SUBFLOOR	Ground Condition	A B C D R MR	Concrete floor on ground
	Ventilation		
	Piles		
	Bearers		
	Joists		
S	Foundation Walls		Concrete
	Insulation		
	Floor		Concrete

A- Very Good B-Good C- Will Need Attention Soon D- Needs Attention Now R- Needs Minor Repair MR- Major Repair Required

Comments:

The concrete foundation is in good condition. There are no signs of cracks or movement.

The timber weather boards finish well clear of the ground.







Services

A- Very Good B-Good C- Will Need Attention Soon D- Needs Attention Now R- Needs Minor Repair MR- Major Repair Required





Summary

Site:

The section has been cut and filled to near level building site. The timber retaining wall is stable and in good condition.

Foundation:

The concrete foundation is in good condition. There are no signs of cracks or movement. Recommend plastering rough concrete finish to base.

Exterior:

The timber weather boards have been fixed over a ventilated cavity system. The weather boards are well painted and in good condition.

Interior:

The interior of the house is generally in good condition.

Windows:

The aluminium windows all have head flashings and are weathertight. Keep exterior door sills and tracks clean and free of debris to help prevent moisture ingress.

Roof:

The coloursteel roof is in good condition. There are no signs of possible leaks. Recommend cleaning the roof.

Services:

The electrics are in good working order. The plumbing is in good working order.

Moisture testing:

Moisture testing was carried out around the skirting boards and windows on all exterior walls using a Surveymaster moisture meter.

A general range of between 8-14% was recorded. All well within acceptable limits.

Conclusion:

The structural integrity of the building is in good order. There are no structural or design defects.

The house is built out of durable materials.

There are no visible or detectable signs of moisture ingress.

It is expected that this house will provide its design of 50 years minimum provided normal maintenance is continued.



CERTIFICATE OF INSPECTION IN ACCORDANCE WITH NZS 4306:2005

Client: Site address:		4 Percy Green Silverdale		
Inspector-	Name: Company: Qualifications:	Robert B Hodges Auckland Home Check Ltd BOINZ Member Licensed Building Practitioner	20120158 BP 108338	
Date of inspect	ion:	21 October 2016		

The following areas of the property have been inspected:

	Yes	No
(a) Site	Ø	
(b) Subfloor	Ø	
(c) Exterior	Ø	
(d) Roof Exterior	Ø	
(e) Roof Space	Ø	
(f) Interior	Ø	
(g) Services	Ø	
(h) Accessory units, ancillary spaces & buildings	Ø	

Any limitations to the coverage of the inspection are detailed in the written report.

Certification:

I hereby certify that I have carried out the inspection of the property site at the above address in accordance with NZS 4306:2005 *Residential property inspection* – and I am competent to undertake this inspection.

3Hodgas

Signature:

Date: 23 October 2016

An inspection carried out in accordance with NZS 4306:2005 is not a statement that a property complies with the requirement of any Act, regulation or bylaw, nor is the report a warranty against any problems developing after the date of the property report. Refer to NZS 4306:2005 for full details.